

15 BRS	S1	(blow or burn or cut or trim) near3 link same (measure\$1 or measuring or measurement or detect\$2 or detecting or detection) near2 voltage	US-PGPUB; USPAT; EPO; JPO; DERWENT	16-Nov-06
202 BRS	S2	(blow or burn or cut or trim) near3 fuse same (measure\$1 or measuring or measurement or detect\$2 or detecting or detection) near2 voltage	US-PGPUB; USPAT; EPO; JPO; DERWENT	16-Nov-06
25 BRS	S4	S3 and (fuse\$1 or link\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	16-Nov-06
42 BRS	S5	S3 and (fusible or trim\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT	16-Nov-06
114 BRS	S8	S6 and (fusible or trim\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT	16-Nov-06
703 BRS	S3	338/92,185,196,198,288,289.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	16-Nov-06
621 BRS	S6	341/121,154.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	16-Nov-06
45 BRS	S7	S6 and (fuse\$1 or link\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	16-Nov-06
223 BRS	S9	323/297,298.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	16-Nov-06
7 BRS	S10	S9 and (fuse\$1 or link\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT	16-Nov-06
9 BRS	S11	S9 and (fusible or trim\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT	16-Nov-06
521 BRS	S12	327/525.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	16-Nov-06
281 BRS	S13	diode near5 (fuse or fusible or link) near5 parallel	US-PGPUB; USPAT; EPO; JPO; DERWENT	30-Mar-07
534 BRS	S15	327/525.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	30-Mar-07
1 BRS	S19	(calibrat\$4 and diode near5 (fuse or fusible or link) near5 parallel).clm.	US-PGPUB; USPAT	30-Mar-07
627 BRS	S17	341/121,154.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	30-Mar-07

704 BRS	S16	338/92,185,196,198,288,289.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	30-Mar-07
224 BRS	S14	323/297,298.ccls.	US-PGPUB; USPAT; EPO; JPO; DERWENT	30-Mar-07
23 BRS	S18	(S14 or S15 or S16 or S17) and @pd>="20061101"	US-PGPUB; USPAT; EPO; JPO; DERWENT	30-Mar-07